



Resicert

Property Inspection Report



Sample Report, WA

Inspection prepared for: Sample Report
Date of Inspection: 8/2/2024 Time: 8:30am
Weather: Fine 24C

Inspector: Resicert Property Inspections
Sample Report

Email: admin@resicert.com

Brilliant inspections, best reports, fast!



Resicert Building and Timber Pest inspections
ACT / NSW / SA / QLD / VIC / WA

Free Call 1800 737 423

Table Of Contents

Items Requiring Attention - Summary	4
Our Services	5
Inspector	6
Inspection Type	7
Inspection Details	8-10
Structural Summary	11
Property Information	12
Foundations	13
Structural Components	14
Internal Roof Space	15-16
Roof	17-21
Interior Areas	22-28
Bathroom and Toilets	29-33
Kitchen	34-37
Laundry	38
Air Conditioner	39
Electrical	40-43
Water Heater	44
Exterior Areas	45-46
Grounds	47-54
Garage	55-56
Pool	57-64
Resicert Service Agreement	65-69





An Overview of the Property Inspection

A property inspection is a non-invasive visual examination of a property, performed for a fee, which is designed to identify observed material defects within specific components of the property. It is intended to assist in evaluation of the overall condition of the property. The inspection is based on observation of the visible and apparent condition of the structure and its components on the date of the inspection and not the prediction of future conditions.

A property inspection will not reveal every concern that exists or ever could exist, but only those material defects observed on the day of the inspection. An Inspection report shall describe and identify in written format the inspected systems, structures, and components of the property and shall identify material defects observed. Inspection reports may contain recommendations regarding conditions reported or recommendations for correction, monitoring or further evaluation by professionals, but this is not required. Within the report you will find items in **RED**. These are items which have been flagged as deficient and require attention. For your safety and liability, we recommend that you hire only licensed contractors when having any work done. Note: If there are no comments in **RED** below, there were no **CRITICAL** system or safety concerns with this property at the time of inspection.

Please carefully read your entire Inspection Report. Call us after you have reviewed your report, so we can go over any questions you may have. Remember, when the inspection is completed and the report is delivered, we are still available to you for any questions you may have, throughout the entire closing process. Properties being inspected do not "Pass" or "Fail." - The following report is based on an inspection of the visible portion of the structure. Important - Please Read Carefully

You will note in the report there is set of boxes next to each section with the following written options across the top: MAINT - PREV - MONIT - DEFR - DEFIC

These are the definitions of these terms which may be selected:

MAINT - MAINTENANCE: A system or component requiring maintenance appears to be functioning as intended, but would benefit from minor repair, service, maintenance or improvement at this time. This may include patching, painting, cleaning, or in some instances a system service by an appropriate specialist.

PREV - PREVENTATIVE: Any improvement to an area, system, component or condition that would help prevent an issue from occurring in the future.

MONIT - MONITOR: An area, condition, system or component that is in need of monitoring appears to be functioning as intended and capable of safe usage in its present condition; however, the inspector's suggests evaluation in the future which would confirm if further action is required.

DEFR - DEFERRED: An area, system, component or condition that is listed as deferred is one that could not be operated or inspected for the reason stated in the report, and may require further evaluation. These may also be items outside our standard of practice, inaccessible or not functional. If required deferred items should be checked prior to settlement during the pre-settlement inspection.

DEFIC - DEFICIENT: A system or component marked as deficient is one that did not respond to user controls, was not able to be safely used, was not functioning as intended, or was otherwise defective. These may be items that are incomplete or have imperfections and with further evaluation these items may (or may not) be found to be material defects. Your inspector does NOT prioritize or emphasize the importance of one deficiency over another. General deficiencies include inoperability, material distress, water penetration, damage, deterioration, missing parts, and unsuitable installation.



Items Requiring Attention - Summary

The summary below consists of potentially significant findings. These findings can be a safety hazard, a deficiency requiring a major expense to correct or items I would like to draw extra attention to. The summary is not a complete listing of all the findings in the report, and reflects the opinion of the inspector. Please review all pages of the report as the summary alone does not explain all of the issues. All repairs should be done by a licensed & bonded tradesman or qualified professional. I recommend obtaining a copy of all receipts, warranties and permits for the work done.

Interior Areas		
Page 24 Item: 4	Smoke Alarms	<ul style="list-style-type: none">• Smoke alarms are out of date 2020 and need to be replaced. Legislation now states that hardwired smoke alarms must be under 10 years old and positioned relative to living and sleeping areas. Installation of new smoke alarms is required to be carried out by the vendors.



Our Services

Check out the full range of Resicert inspection services. For complete details visit our website www.resicert.com by [clicking here](#) or click on the relevant heading below.

Pre-Purchase Inspection: Are you buying a new home? Our pre-purchase building and timber pest inspections will provide you with total peace of mind.

Safety Barrier and Pool Condition Inspection: Effective pool fencing also helps keeps young children safe. This is why pool safety laws are in existence. There are a number of aspects of a swimming pool that require regular attention to ensure they are safe places for all swimmers.

Timber Pest Inspection: A property is normally the largest investment people make in their lifetime, therefore it is important to protect your house (or the house you are about to buy) against timber pests by conducting regular bi-annual or annual inspections.

Retrospective Approval: Quite often additions or modification to a home or building need approval retrospectively –meaning AFTER they have been built.

Handover Defects Inspection - (PCI): Make sure that you are getting what you paid for your new home. This is a detailed inspection undertaken on your new home build before you make your final payment.

Builders Warranty Inspection: Homes that are less than 6 years old require a builder warranty inspection. This then remains with the home for 6 years regardless of ownership. Great way to ensure any issues that can be fixed whilst still under warranty are not missed.

Owner Builder Warranty Inspection: This is when a owner builder wishes to sell their home and builder warranty insurance is required. The insurance company requires a defects report which is what we provide.

Termite Traps - DIY Termite Baiting System: This is a "do it yourself" termite control system - which is generally less than a third of the cost of others systems in the market place. This system will help prevent termites from attacking your home and also treat termite activity.



Inspector

1. Your Inspector

Your Inspector:

- Sample Report

Contact Information:

Email: admin@resicert.com

Mobile: 1800 737 423



Inspection Type

1. Inspection Type

Type:

- Plus - Structural inspection plus good working order inspection
- Safety Barrier and Pool Condition Inspection

Reason:

- Pre-purchase Inspection



Inspection Details

1. Attendance

In Attendance:

- Seller present
- Client not present

2. Occupancy

Occupancy:

- Occupied - Furnished
- Moderate volume of personal and household items observed.
- Access to some items such as: electrical power points, light switches, windows, wall/floor surfaces, appliances and cabinet interiors may be restricted by furniture or personal belongings. Any such items are excluded from this inspection report.



3. Inspection Limitations

Deferred

• 1. Unless we undertake a Timber Pest Inspection as part of your service we will not provide you with information in regards to rodents and timber pests or the possibility of hidden damage or health hazards caused by their presence. We recommend the property is inspected for these conditions by a qualified timber pest inspector, which we can do, in accordance with the latest revision of AS 4349.3. Reporting of mould is limited to the identification of the presence of mould in areas where it is apparent at the time of the inspection. Identification of strains/classifications/types of mould is not possible without sample testing and is excluded from this report.

2. Entering roof spaces that are heavily insulated can cause damage to the insulation and framing. Roof spaces with deep insulation cannot be safely inspected due to limited visibility of the framing members upon which the inspector must walk. In such cases, the roof space is only partially accessed, thereby limiting the review of the attic from the hatch area only. Inspectors will not crawl the roof space when they believe it is a danger to them or that they might damage the insulation or framing. There is a limited review of the roof space viewed from the hatch only in these circumstances. Due to the location and restricted visibility of roof structure tie-down fixings we cannot confirm compliance with AS1684.

3. The roof covering will not be walked upon if in the opinion of the inspector it is not safe to do so. Generally issues that prevent roof access include, access height over 3 metres, steep pitch, wet/slippery surfaces, deteriorated covering. Not being able to walk on the roof significantly limits our inspection which can result in hidden defects going undetected.

4. Any comments in this report relating to asbestos in the property is not exhaustive or conclusive. Asbestos location and assessment is not included as part of our normal inspection process. If you require a comprehensive assessment we recommend that you engage a appropriately qualified specialist contractor.

5. Where a current electrical safety certificate is required, this report does not satisfy or remove the need for that requirement. We are not qualified electrical contractors and can not confirm that electrical components of the inspection full comply or operate with the relevant electrical standards which only a qualified electrical contractor can advise. This also applies to specific requirements and legislation relating to smoke alarms which varies from state to state.

6. Australian Standard AS 4349.1 recognises that a standard property inspection is NOT a warranty. To further protect your interests we strongly advise that you consider insuring your house against undetected structural damage and problems developing with the building structure in the future.

7. It may be a requirement, depending of the location of your property, that the main power is turned off prior to entering the roof space. If we are unable to meet this requirement during the inspection the internal roof space may need to be inspected from the manhole only.



[12-19]



Structural Summary

1. Structural Summary

MAINT	PREV	MONIT	DEFR	DEFIC

Summary:

- As requested, we have conducted a visual structural inspection of the property. The inspection and this report have been undertaken in accordance with the Resicert Inspection Service Agreement.

Generally, this property appears to be in satisfactory structural condition.

Some issues that are considered minor from the viewpoint of structural integrity or are preventative in nature, are addressed under the various headings below.



Property Information

1. Structure Style

Observation:

- Detached
- Single Family Property
- Single Storey Property

2. Property Orientation

Observation:

- The front of the property is facing north.

3. Property Comments

MAINT PREV MONIT DEFR DEFIC

	X		X	
--	---	--	---	--

Observations:

- There have been changes and additions which have been carried out to the original property. Noted patio structure and pool.
- You may wish to confirm that the required council approvals are in place.

Observations:

- We recommend all braided flexible water hoses in the property be checked regularly and replaced as required to prevent water damage.



4. Structure Type

Wall Construction:

- Double Brick with internal cavity

Roof Covering:

- Concrete Tile



Foundations

1. Slab Foundation

MAINT	PREV	MONIT	DEFR	DEFIC

Observations:

- As our inspection is a AS4349.1-2007 visual inspection, we cannot conclusively state the condition of the foundations. Foundations can be subject to various forms of movement such as wetting and drying causing shrinkage and expansion or earth movement. The inspection does not involve physical structural testing of any component of the building nor did it involve excavation of the site or removal and testing of any materials upon the site or components of the structure.
- Visible sections of the concrete slab appeared satisfactory.
- Most areas of the concrete slab not visible due to floor coverings.
- All concrete floor slabs experience some degree of cracking due to shrinkage in the drying process. In most instances floor coverings prevent recognition of cracks or settlement in all but the most severe cases. Where carpeting and other floor coverings are installed, the materials and condition of the flooring underneath cannot be determined.



Structural Components

1. Wall Structure

MAINT	PREV	MONIT	DEFR	DEFIC

Observations

- The wall structure components appeared functional.
- The external walls of the home are of a double brick construction, which contains an internal cavity.

2. Ceiling Structure

MAINT	PREV	MONIT	DEFR	DEFIC

Observations:

- The ceiling structure appeared functional.
- Due to the placement of insulation on the top of the ceilings it is not possible to fully inspect the condition of the ceiling structure and supports. Inspection was limited and based on what was visually accessible at the time of the inspection.



Internal Roof Space

1. Access

MAINT	PREV	MONIT	DEFR	DEFIC

Comments:

- Access was available through a manhole in the bedroom hallway.



2. Duct Work

MAINT	PREV	MONIT	DEFR	DEFIC

Observations:

- Where visible, the air conditioning duct work appeared to be in a satisfactory condition.



3. Insulation

MAINT	PREV	MONIT	DEFR	DEFIC

Materials:

- Fibreglass batts insulation noted in the accessible ceiling space.

Observations:

- Insulation averages about 100mm to 125mm in depth.
- Insulation appears adequate.





4. Exhaust Vent

MAINT	PREV	MONIT	DEFR	DEFIC
	X			

Observations:

- Kitchen exhaust fan terminates in the roof space. You may wish to flue to the outside air to reduce grease buildup in the roof space.
- Bathroom exhaust fan terminates in the roof space. You may wish to flue this to the outside air.



Kitchen extractor pipe.

Roof

1. Roof Structure

MAINT	PREV	MONIT	DEFR	DEFIC

Comments:

- The timber roof structure appears sound.





2. Roof Covering

MAINT	PREV	MONIT	DEFR	DEFIC
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>


Materials:

- Roof was walked upon for the inspection.

Observations:

- The concrete tile roofing material appeared to be in satisfactory condition other than noted.





Noted pool heating pipes.

3. Roof Issues

MAINT	PREV	MONIT	DEFR	DEFIC
X	X			

Materials:

- There are cracks in the bedding cement. This is not unusual for a tiled roof, and is often caused by normal movements in the roof frame. It is recommended that maintenance work is carried out on the roof so that the loose tiles can be re-bedded using flexible bedding compound to help prevent re-cracking.
- There are previous silicone repairs noted. These tiles should be monitored, and ideally at some stage replaced as silicone can deteriorate over time.

Observations:

- The rear roof ventilation fan is noisy in operation. Requires maintenance or replacement.



Noted the rood ventilation fan is very noisy. Recommend maintenance or replacement.





4. Flashing

MAINT	PREV	MONIT	DEFR	DEFIC

Observations:

- Flashing is an impervious material (usually galvanized sheet metal) that comes in a variety of shapes and sizes and is used to cover, waterproof, and direct water away from roof penetrations and from valleys and intersections between the roof covering and other materials.
- The roof flashing, where visible, appears to be in satisfactory condition.



5. Roof Drainage

MAINT	PREV	MONIT	DEFR	DEFIC
X	X			

Observations:

- No major function concerns noted at the time of inspection.
- The gutters should be regularly cleared of debris to ensure the proper flow of water from the roof.



Interior Areas

1. Wall Condition

MAINT	PREV	MONIT	DEFR	DEFIC
X				

Materials:

- Plastered walls noted which appeared functional.

Observations:

- Very minor shrinkage cracks in the wall plaster in some locations. This is not a structural issue and can be repaired normally.
- There is evidence of dampness in the wall which is adjacent to the ensuite shower. This is most likely as a result of the seals and tile joints not functioning correctly. The tiles and joints should be checked for leaks and resealed to prevent any further dampness. Then the wall should be allowed to dry out fully before being sanded/repainted as required. This does not appear to have affected the structural integrity of the wall.



Adjacent to the ensuite shower.

2. Ceiling Condition

MAINT	PREV	MONIT	DEFR	DEFIC
X		X		

Materials:


- There are plasterboard/gyprock ceilings in the home which appear functional.

Observations:

- There is minor cracking which has occurred at the interface between the ceiling cornice and the wall at various locations. This can be a result of foundation settlement and/or movement in the roof structure. This does not appear to have affected the structural integrity of the home and can be repaired normally.
- Some minor sagging was noted in the garage ceiling. This did not appear to have affected the overall structural integrity of the ceiling but might require some maintenance in the future. We recommend that you monitor this area for any further sagging and engage an appropriately qualified tradesperson if the condition worsens.



Slight sagging noted in the garage. Monitor for maintenance.





3. Ceiling Fans

MAINT	PREV	MONIT	DEFR	DEFIC
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Observations:

- Operated normally when tested.



4. Smoke Alarms

MAINT	PREV	MONIT	DEFR	DEFIC
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>

Observations:

- Testing of smoke alarms is not included in this inspection. Pushing the "Test" button only verifies that there is power at the alarm--either a battery or hardwired to the house power--and not the operational workings of the alarm. The operational check is done by filling the sensor with smoke and is beyond the scope of this inspection. Battery operated smoke alarms should be checked routinely and the batteries changed frequently.
- **Smoke alarms are out of date 2020 and need to be replaced. Legislation now states that hardwired smoke alarms must be under 10 years old and positioned relative to living and sleeping areas. Installation of new smoke alarms is required to be carried out by the vendors.**











5. Doors

MAINT	PREV	MONIT	DEFR	DEFIC
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Observations:

- The exterior doors function satisfactorily.
- The interior doors function satisfactorily.





6. Window Condition

MAINT	PREV	MONIT	DEFR	DEFIC



Materials:

- Aluminum framed windows noted.
- Motor driven window shutters were noted.

Observations:

- Windows operated during the inspection appeared functional.
- Window shutters operated during the inspection appeared functional. One controller battery pack present for these shutters.






7. Closets

MAINT	PREV	MONIT	DEFR	DEFIC
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Observations:

- The closets were in serviceable condition at the time of the inspection.





Bathroom and Toilets

1. Toilets

MAINT	PREV	MONIT	DEFR	DEFIC

Observations:

- Operated when tested. No deficiencies noted.



2. Sinks

MAINT	PREV	MONIT	DEFR	DEFIC

Observations:

- The sinks and related components functioned normally when tested.





3. Exhaust Fan

MAINT	PREV	MONIT	DEFR	DEFIC
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Observations:

- The bathroom and toilet exhaust fans responded to normal user controls.



4. Cabinets

MAINT	PREV	MONIT	DEFR	DEFIC
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Observations:

- Appeared functional and in satisfactory condition, at the time of inspection.



5. Heating

MAINT	PREV	MONIT	DEFR	DEFIC
			X	

Observations:

- Heat lamps in ensuite bathroom. At the time of the inspection some of the bulbs were not working and require attention. We recommend you replace the bulb and re-test. If still not functional you will need to consult a qualified electrician to rectify.

6. Showers

MAINT	PREV	MONIT	DEFR	DEFIC

Observations:

- The showers and related components operated normally when tested.




7. Shower Walls

MAINT	PREV	MONIT	DEFR	DEFIC
	X			

Observations:

- As a preventative measure, we suggest that tile grout and joints be sealed to prevent moisture penetration. Failure to keep walls sealed can cause deterioration and extensive moisture damage to the interior walls and surrounding sub-flooring. This damage is not always visible or accessible to the inspector at the time of inspection.





8. Enclosure

MAINT	PREV	MONIT	DEFR	DEFIC

Observations:

- The shower enclosure was functional at the time of the inspection.



9. Bath Tubs

MAINT	PREV	MONIT	DEFR	DEFIC

Observations:

- The bath tub and related components operated normally when tested.





Kitchen

1. Cook top condition

MAINT	PREV	MONIT	DEFR	DEFIC

Observations:

- Gas cook top noted and operated normally when tested.



2. Oven & Range

MAINT	PREV	MONIT	DEFR	DEFIC
X				

Observations:

- The electric oven elements were tested at the time of inspection and appeared to function properly.
- The oven door does not seal properly and requires maintenance.
- The oven door opens fast. Recommend maintenance to the hinges to slow the door down.



The door hinges need adjustment to reduce the door weight.





The rubber door seal is loose. maintenance



The door handle needs tighteneing.

3. Sinks

MAINT	PREV	MONIT	DEFR	DEFIC
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Observations:

- The sink and related components are functional.



4. Counters

MAINT	PREV	MONIT	DEFR	DEFIC
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Observations:

- Appeared functional at the time of inspection.
- Plastic laminate tops noted.
- Some of the areas not visible due to stored personal items.





5. Cabinets

MAINT	PREV	MONIT	DEFR	DEFIC

Observations:

- Appeared functional and in satisfactory condition.



6. Vent Condition

MAINT	PREV	MONIT	DEFR	DEFIC

Materials:

- The built-in vent hood responded normally to user controls.



7. Dishwasher

MAINT	PREV	MONIT	DEFR	DEFIC
			X	

Observations:

- Dishwasher was not tested as this is not within the scope of our inspection. This should be tested at the final pre-settlement inspection.



Laundry

1. Cabinets

MAINT	PREV	MONIT	DEFR	DEFIC

Observations:

- Appeared functional and in satisfactory condition, at the time of inspection.



2. Wash Basin

MAINT	PREV	MONIT	DEFR	DEFIC

Observations:

- The sink and related components are functional unless otherwise noted.



Air Conditioner

1. Reverse Cycle Air Conditioner

MAINT	PREV	MONIT	DEFR	DEFIC

Type:

- The central ducted reverse cycle system responded to normal user controls.



Electrical

1. Electrical Panel

MAINT	PREV	MONIT	DEFR	DEFIC
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Location:

- Main Panel Location:
- West side of the house.

Observations:

- There are at least 2 RCD's installed which protect both the power point and light circuits. This complies with current regulatory requirements.



2. Photo Voltaic Panels

MAINT	PREV	MONIT	DEFR	DEFIC
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>

Materials:

- There is a photo voltaic (solar panels) power system located on the roof.

Observations:

- The inverter for the PV system was located on the exterior west side of the home and appears to be functioning.
- As part of the inspection we can not confirm the effectiveness of the solar panel system.



3. Power points

MAINT	PREV	MONIT	DEFR	DEFIC

Comments:

- All tested interior and exterior power points were functional unless otherwise noted.
- Our inspection was limited to visible and accessible outlets only. Those outlets that were concealed or inaccessible due to stored items, furniture, etc. were not tested or inspected. Only a representative sampling of outlets were tested.





4. Lights and Switches

MAINT	PREV	MONIT	DEFR	DEFIC
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Comments:

- All tested interior and exterior light fixtures and switches were functional unless noted.
- Some low voltage lights were noted in the property.





5. Internal Roof Wiring

MAINT	PREV	MONIT	DEFR	DEFIC
	X			

Materials:

- It was noted that there are downlights but no barriers in place to separate these from the insulation. This would not comply with current standards. To improve the safety you may wish to consider installing appropriate barriers or replacing these with LEDs for safety and efficiency in the future.

Water Heater

1. Water Heater Condition

MAINT	PREV	MONIT	DEFR	DEFIC
		X		

Heater Type:

- Gas boosted solar hot water heater.

Location:

- Exterior.
- Roof.

Observations:

- Please note that we only inspect & comment on the operational and safety issues of the hot water system. Issues relating to compliance to relevant codes and standards, and/or installation compliance is excluded from the scope of the inspection.
- No major system safety or function concerns noted at time of inspection.
- Monitor the roof panels, slight moisture stain noted below these panels. It may be condensation. You may wish to have these checked



Noted small moisture stain, monitor this are. May be condensation.



Exterior Areas

1. Window Condition

MAINT	PREV	MONIT	DEFR	DEFIC

Observations:

- Components appeared in satisfactory condition at the time of inspection.



2. Eaves & Fascia

MAINT	PREV	MONIT	DEFR	DEFIC

Observations:

- The eaves are in satisfactory condition.

3. Walls

MAINT	PREV	MONIT	DEFR	DEFIC
	X			

Materials:

- The brick wall covering is in a satisfactory condition.

Observations:

- There are a number of garden beds which are adjacent to the external walls. This can result in water moisture affecting the structure over time. If these beds are retained it is important that any watering is directed away from the building and kept to an absolute minimum and is controlled.



4. Exterior Paint

MAINT	PREV	MONIT	DEFR	DEFIC
X	X			

Observations:

- All exterior painted wood trim surfaces should be annually examined and sealed, re-caulked and re-painted as needed.
- All exterior painted metal surfaces should be annually examined and cleaned, primed with rust inhibitor and re-painted as needed.



Grounds

1. Driveway and Walkway Condition

MAINT	PREV	MONIT	DEFR	DEFIC

Materials:

- Concrete driveway noted.
- Concrete pathways noted.
- Pathways in good shape for age and wear. No deficiencies noted.
- Driveway in reasonable shape for age and wear. No major deficiencies noted.






2. Grading and Drainage

MAINT	PREV	MONIT	DEFR	DEFIC

Observations:

- Surface drainage conditions within 3 metres of the inspected structure appeared satisfactory.






3. Vegetation Observations

MAINT	PREV	MONIT	DEFR	DEFIC
	X			

Observations:

- Prune or remove any plants that are in contact or proximity to home to eliminate pathways of wood destroying insects.



4. Fence Condition

MAINT	PREV	MONIT	DEFR	DEFIC

Materials:

- Metal.
- Unless otherwise noted, the perimeter fence appeared functional at the time of the inspection.






5. Gate Condition

MAINT	PREV	MONIT	DEFR	DEFIC
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Materials:

- Metal gates in good condition.




6. Patio and Porch Decks

MAINT	PREV	MONIT	DEFR	DEFIC
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Observations:

- Deck was examined and appears in satisfactory and functional condition with normal wear for its age. Appears to be a sound structure.
- Deck Substructure Inspection excluded, due to limited access because of low height or obstructions.






7. Patio & Pergola

MAINT	PREV	MONIT	DEFR	DEFIC
X				

Observations:

- One area of the patio frame has surface rust and require maintenance.
- Noted that the external alfresco ceiling is gyprock sheeting. It is important to keep this material well sealed and painted to prevent the ingress of moisture into the sheet material and taped joints.



Some corrosion noted at the patio outside the laundry. Recommend maintenance.





8. Yard Walls


MAINT	PREV	MONIT	DEFR	DEFIC
X				

Materials:

- Limestone retaining walls.

Observations:

- The yard walls appear to be functional and structurally sound.
- Evaluation of retaining wall strength, adequacy, and drainage falls outside the scope of a Resicert building inspection. Such evaluation will require the services of a geotechnical engineer. Our evaluation is limited to reporting significant defects that are visible and apparent at the time of the inspection.
- Some cracks noted in external yard walls. This does not appear to have affected the overall structural integrity of the walls but will require some maintenance at some point.



Noted the gate post pier is open at the top. You may wish to cap this with a slab

9. Main Gas Valve Condition

MAINT	PREV	MONIT	DEFR	DEFIC

Location:

- Side of structure.

Observations:

- Main gas shut off located at outside meter.





10. Plumbing



MAINT	PREV	MONIT	DEFR	DEFIC
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Materials:

- Water tanks noted on the property.

Observations:

- The water tank appeared serviceable and in good condition at the time of the inspection.



11. Sprinklers

MAINT	PREV	MONIT	DEFR	DEFIC
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>

Observations:

- Sprinkler system was noted. It is not tested as part of the inspection. This should be tested at the final settlement inspection.



Garage

1. Garage and Shed

MAINT	PREV	MONIT	DEFR	DEFIC
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Materials:

- The attached brick garage appears structurally sound.
- The rear metal shed appears to be structurally sound.



2. Garage Door Condition

MAINT	PREV	MONIT	DEFR	DEFIC
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Materials:

- Sectional door noted.

Observations:

- No deficiencies observed.





3. Garage Opener Status

MAINT	PREV	MONIT	DEFR	DEFIC
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Observations:

- Appeared functional using normal controls, at the time of inspection.



Pool

1. Deck Condition



MAINT	PREV	MONIT	DEFR	DEFIC
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Materials:

- Limestone concrete located around pool area.

Observations:

- Deck was examined and appears in satisfactory and functional condition with normal wear for its age. Appears to be a sound structure.



2. Structure Condition

MAINT	PREV	MONIT	DEFR	DEFIC
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>


Materials:

- Below ground.
- Salt water chlorination.

Materials: Concrete.

Observations:

- Some surface staining was noted on the walls.




3. Water Condition

MAINT	PREV	MONIT	DEFR	DEFIC
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Materials:

- Clear.





4. Pool Barrier Condition

MAINT	PREV	MONIT	DEFR	DEFIC




Materials:

- Metal fence.
- BCA 2010 – Volume 1; Performance Requirement GP1.2
A barrier must be provided to a swimming pool and must:
 - i. be continuous for the full extent of the hazard; and
 - ii. be of a strength and rigidity to withstand the foreseeable impact of people; and
 - iii. restrict the access of young children to the pool and the immediate pool surrounds; and
 - iv. have any gates and doors fitted with latching devices not readily operated by young children, and constructed to automatically close and latch.
- Safety barriers: A swimming pool associated with a Class 2 or 3 building or Class 4 part of a building or a children's service, with a depth of water more than 300 mm, must have fencing or other barriers in accordance with AS1926 Parts 1 and 2.
- The gate shall close and latch from any position from resting on the latching mechanism to fully open, under both of the following conditions:
 - (i) Under the natural weight of the gate.
 - (ii) After a mass of 25 kg supported by the top rail is placed at a point 100 mm from the outer edge of the locking stile of the gate.

Observations:

- The pool barrier appears to be satisfactory and to comply with the required regulations. For confirmation, please consult with a pool fencing specialist.






5. Pumps

MAINT	PREV	MONIT	DEFR	DEFIC
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Observations:

- Operated normally when tested.
- The main pool pump and the chlorinator controller have been replaced the seller stated.





6. Jets

MAINT	PREV	MONIT	DEFR	DEFIC

Observations:
 • Operated.



7. Return System Observations

MAINT	PREV	MONIT	DEFR	DEFIC

Materials:
 • A water recirculation system in a swimming pool with a depth of water more than 300mm must:
 i. for a spa pool, comply with AS 1926.3 except the specified distance between two outlets connected to a common line may be not less than 600mm; and
 ii. for all other swimming pools, comply with AS 1926.3.
 Observations:
 • The return was noted to be in satisfactory condition.





8. Pool Heater


MAINT	PREV	MONIT	DEFR	DEFIC
		X	X	

Materials:

- A solar pool water heating system was noted.

Observations:

- The solar heating system was not tested as it is not within the scope of our inspection.



New heater tubing system has been installed in the last two years. Monitor for leaks as this carries salt water.



Old system still present.






Not tested in our inspection.

9. Lights

MAINT	PREV	MONIT	DEFR	DEFIC
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Observations:

- Operated at the time of the inspection.



10. Pool Cover Observations

MAINT	PREV	MONIT	DEFR	DEFIC
<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Materials:

- Pool covers offer protection for the pool from sun damage, debris and evaporation.

Observations:

- The pool cover appears to be in satisfactory condition for its age. Noted three pieces.
- The pool cover should have an external white cover fitted when stored on the roller to prevent sun damage.





11. Safety Signs/Equipment Observations

MAINT	PREV	MONIT	DEFR	DEFIC
	X			

Materials:

- The Royal Life Saving Society Australia recommends that all home pool owners display of a CPR Step Chart in the swimming pool area and in other strategic locations within the home.
- Depth Indicators

To enable all users (residents or guests) to make appropriate behaviour decisions it is recommended that changes to pool depth are clearly communicated through placement of indicators; especially at shallow and deep ends.

Where the pool exceeds 12.5m in length or has a sloping gradient that exceeds 1:15; then indicators should be marked at intervals not exceeding 7m.

Depth indicators should contrast against their background with lettering that is 50mm in size (+/- 5mm).

Depth indicators should be metric

Depth indicators should not be placed so that no part is below the water line. Carefully consider the layout of your pool when deciding the placement that the indicator is most likely to be seen. Entry and exit points of the are high priorities.

- Emergency Care

A basic first aid kit should be located close to the pool area. Either the container or its location should be clearly identified using recognised symbols. Australian Standards describe the elements of this sign as being:

A green cross on a white background or reversed with a white cross on a green background.

Where text is required this should have the same colour configurations as described immediately above and should clearly state "First Aid".

Use of symbols is preferred over text.

Close proximal location of this emergency care equipment to a telephone should be given consideration.

Observations:

- No CPR sign was present at the time of the inspection.
- No depth indicators were present at the time of the inspection.
- No First Aid kit was present in the pool area at the time of the inspection.



Resicert Service Agreement

Resicert Inspection and Service Agreement - March 2024

1.0 Acceptance of Agreement : The Client has made a booking, accepted the quotation and the inspector arrives on site to commence the inspection, the Client is deemed to accept this agreement as to the basis of the inspection being undertaken. This agreement takes precedence over any previous oral or written representations by Resicert.

2.0 Payment Terms : Full payment of the inspection is required prior to the inspection report and summary being provided to the Client.

3.0 Purpose of Inspection : The purpose of the inspection is to provide advice to the Client in relation to the condition of the property at the time of the inspection. This report is not an all encompassing report dealing with the building from every aspect. It is a reasonable attempt to identify any obvious or significant defects apparent at the time of the inspection.

4.0 Scope of Inspection : Scope of inspection will depend on the inspection type which the Client has selected. Pre-purchase inspections are undertaken in accordance with AS 4349.1 - 2007 - Inspection of buildings
Part 1: Pre-purchase inspections— Residential buildings - unless otherwise stated in the numbered clauses below. Pre-purchase property inspections do not inspect to or comment on building codes, as building codes for different structural areas change regularly. Pre purchase property inspections are designed to offer an informed opinion on what is visibly apparent on the date of inspection.

Timber Pest Inspections are undertaken in accordance with AS 4349.3-2010 - Inspection of Buildings - Part 3 - Timber Pest Inspections. 'Sounding' will be used as a method of inspection where practical and possible. Resicert Pest Inspectors conduct detailed but non-invasive Timber Pest Inspections, but are not Pest Controllers. Rodents, Spiders or other Pests do not form a part of our Inspection process, our Inspectors purely seek to investigate presence of (or past evidence of) Timber Pest Inspects, including but not limited to Termites and Borers.

4.1 Basic and Standard Inspections : The inspection shall comprise visual appraisal and limited assessment of accessible areas of the property to identify major defects to the building structure and to form an opinion regarding the general condition of the structure of the property.

It is not required to contain any assessment or an opinion regarding the following:

-Any non-structural element, e.g., roof plumbing and roof covering, general gas, water and sanitary plumbing, electrical wiring, partition walls, cabinetry, windows, doors, trims, fencing, minor structures, non-structural damp issues, ceiling linings, floor coverings, decorative finishes such as plastering, painting, tiling, etc. -An assessment of any aspect or component of the property that cannot be seen or that requires testing and/or measurement to determine soundness. - Any area or item that was not, or could not be, observed by the inspector. -General maintenance other than that which is deemed to be directly related to the ongoing structural performance of the property. -Serviceability damp defects such as condensation, rising damp, lateral damp, falling damp should only be assessed and reported on where structural damage



has occurred, is occurring, or may occur.

4.2 Plus Inspection : Resicert shall inspect accessible parts of the building and appurtenances, together with relevant features of the property within 30m of the building and within the boundaries of the site, or as otherwise agreed in the inspection agreement. In this context, relevant features include car accommodation, detached laundry, and garden sheds, retaining walls more than 700 mm high, paths and driveways, steps, fencing, earth embankments, surface water drainage and storm water run-off.

4.3 Safety Barrier and Pool Condition Inspection (WA) as an add-on or stand alone: Inspection is completed in accordance with the Western Australian Private Swimming Pool Inspector Guidelines Inspecting Private Swimming Pool Spa Enclosures Second edition 24 July 2007 / Pool Safety Inspection (QLD, NSW &VIC) as a Compliance Inspection or Advisory only: inspection and report in accordance with AS1926 1&2-2007 and QDC MP3.4: Inspector has the right not to test or inspect any component if they believe that through operation or testing it may cause damage or is a potential safety issue. -Require permission, necessary access and any required components to operate or inspect items as outlined for this inspection - Unless otherwise advised we will assume that all components can be operated and will not be damaged when doing so. No liability relating to operating a component during the inspection. - Require applicable operational manual and/or instructions relating to the inspection of any component. -If we are required to start up or turn on any component, it will be necessary to have required start up information. Otherwise we reserve the right not to operate. -information contained in the WA Safety Barrier and Pool Condition Report (as an add-on or a stand alone) or a QLD NSW &VIC Advisory Only Report is an information document only and will articulate potential issues that are likely to be flagged as deficient by council in the process of achieving required certification for the pool. It is not always possible to operate pumps. For pools and spas (excluding bath type spas located in bathrooms) to be tested must have a minimum level of water prior to commencement of inspection. Resicert accepts no liability for any subsequent drownings or accidents resulting in death or injury that may result from the advise provided in the Safety Barrier and Pool Condition Report. The Recommendations made in the report are for information only and Resicert will not seek compliance on behalf of any third party.

4.4 SMOKE ALARMS - (QLD) it is a requirement from 31 December 2021 that all rental properties are fitted with interconnected photoelectric smoke alarms, and from 31 December 2026 that all homes are fitted with interconnected photoelectric smoke alarms. These alarms must be installed in every bedroom, in hallways and on every level.

5.0 Extent of Reporting : Significant items to be reported are as follows: (a) Major defects as defined in AS 4349.1. (b) A general impression regarding the extent of minor defects. (c) Any major defect that is an urgent and a serious safety hazard.

6.0 Safe and Reasonable Access : This is a visual inspection only. The extent of accessible areas shall be determined by the inspector at the time of inspection, based on the conditions encountered at the time of inspection. The inspector shall also determine whether sufficient space is available to allow safe access. This will apply to roof spaces and underfloor access. The inspection shall include only accessible areas and areas that are within the inspector's line of sight and close enough to enable reasonable appraisal. Roof inspection by walking upon the roof will be limited to single storey dwellings which are safely accessible with the use of a 3.6 metre ladder, and only when the slope, roof condition and climate do not reduce safety.



7.0 Exclusions from Inspection : Resicert need not inspect or report on the following items:Footings below the ground or concealed damp-proof course - the structural design or adequacy of any element of construction. - Electrical installations, smoke detectors, light switches and fittings, TV, sound and communications - Concealed plumbing, gas fittings and fixtures. - Whether the building complies with the provisions of any building Act, code, regulation(s) or by-laws. - Air-conditioning , alarm and intercom systems, automatic garage door mechanisms. - Swimming pools, pool fencing and associated filtration and similar equipment. - The operation of fireplaces and solid fuel heaters, including chimneys and flues. - Soft floor coverings. - Electrical appliances including dishwashers, incinerators, ovens, ducted vacuum - Paint coatings, except external protective coatings. - Health hazards (e.g., allergies, soil toxicity, lead content, presence of asbestos). - Timber and metal framing sizes and adequacy and concealed tie-downs and bracing. - Timber pest activity. - Other mechanical or electrical equipment (such as gates, inclinators). - Soil conditions and control joints. - Sustainable development provisions. - Concealed framing-timbers or any areas concealed by wall linings/ sidings. - Lands

For Western Australian Residential Properties built pre-1970's, we recommend an electrical inspection to ensure the Roof cabling is satisfactory.

8.0 Liability and Limitations : The inspection shall comprise visual assessment of the property to identify major defects and to form an opinion regarding the general condition of the property at the time of inspection. The Resicert report does not constitute a guarantee in relation to the property. It is a limited opinion of condition of the inspected property at the time of inspection.

Property conditions can change significantly over time, particularly under severe weather conditions and extremes of temperature. Therefore our Reports are only valid for a period of 60 days following the date of Inspection.

Resicert's liability in relation to the inspection and report will be limited to a refund of the inspection fee. The inspection and report is undertaken for the Client named on the report. No responsibility is accepted to any third party.

9.0 Money Back Guarantee : If the client is not fully satisfied with the building inspection and/or building inspection report provided, Resicert will refund 100% of the building inspection fee to the client. This will require the client to complete the request for a refund application form and agree to the conditions there-in stated prior to a refund. This guarantee only applies for a period of 60 days from the date of the inspection. After this period it is at the full discretion of Resicert whether a request for a refund will be approved.

10.0 Follow up inspections : The initial fee does not allow for any follow up visits, if required, to the residence. A quote to undertake this activity will be provided if necessary.

11.0 Estimates Provided : Any estimates or budgets provided relating to work required to be undertaken is purely to provide an indication of approximate costings. The figures provided are not a quotation or estimate to carry out any works and can not be relied upon for this purpose. All estimates and budgets which are provided are done so only on this basis, and no liability, with the client or any third party, whatsoever will be accepted in relation to budgets and estimates provided, unless otherwise stated.

12.0 Probable Costings : Any probable costings outlined represent an opinion of renovation costs only which can vary considerably depending on range of factors including but not limited to:



Type and standard of materials, fittings and fixtures chosen. -Level of of client involvement and engagement required - Construction method and process chosen -Overall timings and duration of works undertaken -Fluctuations in building materials and labour costs -Scale and extent of the renovation project -When the renovation project is undertaken - Location of the works and site conditions

The probable costings provided is based on standard rates for previous projects and is not an elemental or detailed estimate. A detailed estimate of this nature can be provided by a Quantity Surveyor or through obtaining quotations from appropriate suppliers and tradesman.

13.0 Approvals for access to property : The Client represents and assures Resicert that the Client has secured all approvals necessary for entry onto the premises to be inspected. Client further agrees to defend, indemnify and hold harmless Resicert from demands or claims alleging a trespass upon the premises to be inspected. It is the responsibility of the Client or Agent to ensure the utilities are on at the time of inspection. Resicert recommends checking for permits on all additional construction performed on the property after the original construction.

14.0 Depreciation Schedules : Resicert works in conjunction with a Quantity Surveyor to provide Depreciation Schedules for Investment Properties. The Quantity Surveyor is a third party and both logos (Resicert and the third party) will be listed at the top of the report. (2) Resicert holds Professional Indemnity Insurance for Depreciation Schedules, but the tax calculation provided by the Quantity Surveyor is entirely under the provision of the Quantity Surveyor used and Resicert cannot and does not accept liability in relation to any tax calculations.

15.0 Proprietary Rights: The report, contents, comments and format of this inspection report are the proprietary rights of Resicert Property Inspections and subject to copyright law. Unlawful duplication can result in penalties.

16.0 Asbestos Disclaimer: If during the course of the inspection asbestos or materials containing asbestos happened to be noticed then this may be noted. Many building materials for many years contained or were comprised entirely of asbestos material. Approximate dates for legal disuse include: sprayed/lagging - late 1970s, cement sheeting - 1982, corrugated sheeting - 1984, other asbestos cement products - 1986, gaskets - 1997, friction pads - 2003. While your inspector may indicate that there may be some suspected asbestos material at the property, any property constructed prior to 2004 may have elements of asbestos in the materials, lagging, insulation, cement sheeting, piping, floor coverings, floor underlay, expansion joints, caulking, sink pads, toilet systems, pipe insulation, gaskets, gasket insulation and more materials and locations around the home. The only conclusive way to determine if asbestos is present in the home or as a part of the materials in the home is to take a sample and have it professionally tested. This sampling falls outside of the scope of this inspection. Sheetting and asbestos materials should fully sealed. If it is damaged, it should be dealt with immediately. If asbestos is noted as present within the property you should then seek advice from a qualified asbestos removal expert for further details and information on this material. Drilling, cutting or removing products containing asbestos is a high risk to peoples health and the Client should seek advice from a qualified asbestos removal expert.

17.0 Not a "Certificate of Building Compliance" report (For reports within ACT): The report may contain copies of any approved plans, building approvals, building permit and Certificates of Occupancy and act as a compliance report for the purposes of "Building and Compliance". However, any comments made by the person who prepared the report as to



whether or not, in the opinion of the inspector, the structures on the land substantially comply with the approved plans (if any) are made on the basis of a review of the plans and the visually accessible parts of the property at the time of the inspection.

18.0 Ownership rights :Resicert retains ownership and all rights to the inspection report. Resicert has the rights to all data collected during the inspection and compiled in the report. Resicert has the right to on-sell the inspection report to 3rd parties subject to removal of any specific Client details. All rights reserved.

19.0 In the event that a defect is identified that has not been documented in this report, Resicert must be notified before any remedial work is undertaken. No Liability shall be accepted where remedial action is taken prior to Resicert being advised of the defect and given the opportunity to re-inspect the property and identify the defect.

[10-17]



Glossary

Term	Definition
Valley	The internal angle formed by the junction of two sloping sides of a roof.

