

Property Inspection Report



Sample Report, WA

Inspection prepared for: Sample Report
Date of Inspection: 21/12/2021 Time: 09:00 AM
Weather: Fine 24C

Inspector: Sample Report

Email: admin@resicert.com www.resicert.com.au

Brilliant inspections, best reports, fast!



Table Of Contents

Items Requiring Attention - Summary	4
Our Services	5
Inspector	6
Inspection Type	6
Inspection Details	6
Structural Summary	6
Property Information	7
Foundations	7
Structural Components	8
Internal Roof Space	9
Roof	10-11
Interior Areas	12-15
Bathroom and Toilets	16-17
Kitchen	18-20
Laundry	21
Electrical	22-23
Gas	24
Water Heater	24
Exterior Areas	25-26
Grounds	27-28
Garage	29
Resicert Service Agreement	30-34
Glossary	35



An Overview of the Property Inspection

A property Inspection is a non-invasive visual examination of a property, performed for a fee, which is designed to identify observed material defects within specific components of the property. It is intended to assist in evaluation of the overall condition of the property. The inspection is based on observation of the visible and apparent condition of the structure and its components on the date of the inspection and not the prediction of future conditions.

A property inspection will not reveal every concern that exists or ever could exist, but only those material defects observed on the day of the inspection. An Inspection report shall describe and identify in written format the inspected systems, structures, and components of the property and shall identify material defects observed. Inspection reports may contain recommendations regarding conditions reported or recommendations for correction, monitoring or further evaluation by professionals, but this is not required. Within the report you will find items in RED. These are items which have been flagged as deficient and require attention. For your safety and liability, we recommend that you hire only licensed contractors when having any work done. Note: If there are no comments in RED below, there were no CRITICAL system or safety concerns with this property at the time of inspection.

Please carefully read your entire Inspection Report. Call us after you have reviewed your report, so we can go over any questions you may have. Remember, when the inspection is completed and the report is delivered, we are still available to you for any questions you may have, throughout the entire closing process. Properties being inspected do not "Pass" or "Fail." - The following report is based on an inspection of the visible portion of the structure.Important - Please Read Carefully

You will note in the report there is set of boxes next to each section with the following written options across the top: MAINT - PREV - MONIT - DEFR - DEFIC

These are the definitions of these terms which may be selected:

MAINT - MAINTENANCE: A system or component requiring maintenance appears to be functioning as intended, but would benefit from minor repair, service, maintenance or improvement at this time. This may include patching, painting, cleaning, or in some instances a system service by an appropriate specialist.

PREV - PREVENTATIVE: Any improvement to an area, system, component or condition that would help prevent an issue from occuring in the future.

MONIT - MONITOR: An area, condition, system or component that is in need of monitoring appears to be functioning as intended and capable of safe usage in its present condition; however, the inspector's suggests evaluation in the future which would confirm if further action is required.

DEFR - DEFERRED: An area, system, component or condition that is listed as deferred is one that could not be operated or inspected for the reason stated in the report, and may require further evaluation. These may also be items outside our standard of practice, inaccessible or not functional. If required deferred items should be checked prior to settlement during the pre-settlement inspection.

DEFIC - DEFICIENT: A system or component marked as deficient is one that did not respond to user controls, was not able to be safely used, was not functioning as intended, or was otherwise defective. These may be items that are incomplete or have imperfections and with further evaluation these items may (or may not) be found to be material defects. Your inspector does NOT prioritize or emphasize the importance of one deficiency over another. General deficiencies include inoperability, material distress, water penetration, damage, deterioration, missing parts, and unsuitable installation.



Items Requiring Attention - Summary

The summary below consists of potentially significant findings. These findings can be a safety hazard, a deficiency requiring a major expense to correct or items I would like to draw extra attention to. The summary is not a complete listing of all the findings in the report, and reflects the opinion of the inspector. Please review all pages of the report as the summary alone does not explain all of the issues. All repairs should be done by a licensed & bonded tradesman or qualified professional. I recommend obtaining a copy of all receipts, warranties and permits for the work done.



Our Services

Check out the full range of Resicert inspection services. For complete details visit our website www.resicert.com by clicking here or click on the relevant heading below.

Pre-Purchase Inspection: Are you buying a new home? Our pre-purchase building and timber pest inspections will provide you with total peace of mind.

Safety Barrier and Pool Condition Inspection: Effective pool fencing also helps keeps young children safe. This is why pool safety laws are in existence. There are a number of aspects of a swimming pool that require regular attention to ensure they are safe places for all swimmers.

Timber Pest Inspection: A property is normally the largest investment people make in their lifetime, therefore it is important to protect your house (or the house you are about to buy) against timber pests by conducting regular bi-annual or annual inspections.

Retrospective Approval: Quite often additions or modification to a home or building need approval retrospectively –meaning AFTER they have been built.

Handover Defects Inspection - (PCI): Make sure that you are getting what you paid for your new home. This is a detailed inspection undertaken on your new home build before you make your final payment.

Builders Warranty Inspection: Homes that are less than 6 years old require a builder warranty inspection. This then remains with the home for 6 years regardless of ownership. Great way to ensure any issues that can be fixed whilst still under warranty are not missed.

Owner Builder Warranty Inspection: This is when a owner builder wishes to sell their home and builder warranty insurance is required. The insurance company requires a defects report which is what we provide.

Termite Traps - DIY Termite Baiting System: This is a "do it yourself" termite control system - which is generally less than a third of the cost of others systems in the market place. This system will help prevent termites from attacking your home and also treat termite activity.





Inspector

1. Your Inspector

Your Inspector:

Robert Fleming

Contact Information:

Email: rfleming@resicert.com

Mobile: 0451 157 701

Inspection Type

1. Inspection Type

Type:

• Plus - Structural inspection plus good working order inspection

Reason:

Pre-purchase Inspection

Inspection Details

1. Attendance

In Attendance:

- Client present
- Agent present

2. Occupancy

Occupancy:

- Vacant Unfurnished
- No personal or household items observed.

Structural Summary

1. Structural Summary

MAINI	PREV	MONII	DEFR	DEFIC

Summary:

• As requested, we have conducted a visual structural inspection of the property. The inspection and this report have been undertaken in accordance with the Resicert Inspection Service Agreement.

Generally, this property appears to be in satisfactory structural condition.

Some issues that are considered minor from the viewpoint of structural integrity or are preventative in nature, are addressed under the various headings below.



Property Information

1. Structure Style

Observation:

- Attached
- Single Family Property
- Townhouse
- Double Storey Property

2. Property Orientation

Observation:

- Generally the direction is determined by the location of the front door.
- The front of the property is facing southeast.

3. Structure Type

Wall Construction:

- Double Brick with internal cavity
- Roof Covering:
- Clay Tile

Foundations

1. Slab Foundation

IVIZALIATI	1 1 L	IVICIALI	DELLIK	DELLIO

- As our inspection is a AS4349.1-2007 visual inspection, we cannot conclusively state the condition of the foundations. Foundations can be subject to various forms of movement such as wetting and drying causing shrinkage and expansion or earth movement. The inspection does not involve physical structural testing of any component of the building nor did it involve excavation of the site or removal and testing of any materials upon the site or components of the structure.
- Any significant tree within close proximity to the structure may have an influence upon the foundation material/footings and if applicable we would recommend that further advice be sought from an expert.
- Visible sections of the concrete slab appeared satisfactory.
- Most areas of the concrete slab not visible due to floor coverings.
- All concrete floor slabs experience some degree of cracking due to shrinkage in the drying process. In most instances floor coverings prevent recognition of cracks or settlement in all but the most severe cases. Where carpeting and other floor coverings are installed, the materials and condition of the flooring underneath cannot be determined.








Structural Components

1. Wall Structure

MAINT PREV MONIT DEFR

Observations

- The wall structure components appeared functional.
 The external walls of the home are of a double brick construction, which contains an internal cavity.





2. Ceiling Structure
MAINT PREV MONIT DEFR DEFIC Observations:

• The ceiling structure appeared functional.








Internal Roof Space

1. Access

MAINT	PREV	MONIT	DEFR	DEFIC	2
					Comments:
					 Access was available through a manhole in the bedroom hallway.



2. Insulation Issues

MAINT PREV MONIT DEFR DEFIC

X

X

Materials:

• There is no insulation on the ceiling in the roof space. Expect higher heating and cooling energy costs. It is recommended that insulation be added to improve the thermal efficiency of the home.







Roof

1. Roof Structure

Comments:

The timber roof structure appears sound.





2. Roof Covering

MAINI	PREV	MONII	DEFR	DEFIC
				l
				l

Materials:

- Roof was walked upon for the inspection.
- Observations:
- TV Antennae noted on the roof.
- The clay tile roof covering appears to be in satisfactory condition other than noted.








3. Roof Issues

MAINT	PREV	MONIT	DEFR	DEFIC
IXI		IXI		

Materials:

• A number of capping tiles are loose due to cracks in the bedding cement. This is not unusual for a tiled roof, and is often caused by normal movements in the roof frame. It is recommended that maintenance work is carried out on the roof so that the loose tiles can be re-bedded using flexible bedding compound to help prevent re-cracking.



4. Flashing

MAINI	PREV	MONII	DEFR	DEFIC

- Flashing is an impervious material (usually galvanized sheet metal) that comes in a variety of shapes and sizes and is used to cover, waterproof, and direct water away from roof penetrations and from valleys and intersections between the roof covering and other materials.
- The roof flashing, where visible, appears to be in satisfactory condition.
- Some of the <u>valley flashing</u>s have some leaf debris which should be cleared out.






5. Roof Drainage

MAINT	PREV	MONIT	DEFR	DEFIC
Χ		Х		

Observations:

No major function concerns noted at the time of inspection.
The gutters should be regularly cleared of debris to ensure the proper flow of water from the roof. Currently need cleaning.










Interior Areas

1. Wall Condition

MAINT PREV MONIT DEFR DEFIC Materials: • Plastered walls noted which appeared functional.








2. Ceiling Condition

NA - (! - I -	DEFIC	DEFR	MONII	PREV	MAINI
Materials					
. The see a	l 1				

• There are plasterglass ceilings in the home which appear functional.





3. Smoke Alarms

MAINT	PREV	MONIT	DEFR	DEFIC	
			X		

- Testing of smoke alarms is not included in this inspection. Pushing the "Test" button only verifies that there is power at the alarm--either a battery or hardwired to the house power--and not the operational workings of the alarm. The operational check is done by filling the sensor with smoke and is beyond the scope of this inspection. Battery operated smoke alarms should be checked routinely and the batteries changed frequently.
- There is a hardwired smoke alarm installed in the bedroom hallway area. Smoke alarm due for replacement in 2031.








4. Doors

MAINI	PREV	MONII	DEFR	DEFIC
				l
				l

Observations:

- The exterior doors function satisfactorily.
 The interior doors function satisfactorily.



5. Window Condition

MAINT	PREV	MONIT	DEFR	DEFIC
Χ		Х		

Materials:


- Aluminum framed windows noted.Aluminum louvers noted.

- Windows operated during the inspection appeared functional.
 Cracked glass noted in the 2nd floor bedroom. Requires maintenance.









bedroom

6. Floor Coverings MAINT PREV MONIT DEFR DEFIC

Materials:

The floor coverings are functional.







Bathroom and Tollets
1. Toilets
Observations: Operated when tested. No deficiencies noted.
2. Sinks
Observations: The sink and related components functioned normally when tested.
3. Exhaust Fan
Observations: The bathroom exhaust fan responded to normal user controls.

4	\sim		
7	1.0	hin	ets
4	(,,	ОШ	1612

MAINT	PREV	MONIT	DEFR	DEFIC	Observations:
					 Appeared functional and in satisfactory condition, at the time of inspection.

5. Counters

	J. U	Carr	.0.0			
1	MAINT	PREV	MONIT	DEFR	DEFIC	Observations:
Γ						Observations:
				l		• No major discrepancies noted in the counter tops and surfaces. There is
L						
						normal wear, consistent with their age.






6. Heating

MAINI	PREV	MONII	DEFR	DEFIC

Observations:
• Heat lamps in the bathroom functioned normally.




7. Showers

MAINI	PREV	MONII	DEFR	DEFIC	
					П
		l		l	ı
		l		l	L

Observations:

• The shower and related components operated normally when tested.





8. Shower Walls

MAINT	PREV	MONIT	DEFR	DEFIC
				l

Observations:

- As a preventative measure, we suggest that tile grout and joints be sealed to prevent moisture penetration. Failure to keep walls sealed can cause deterioration and extensive moisture damage to the interior walls and surrounding sub-flooring. This damage is not always visible or accessible to the inspector at the time of inspection.
- No discrepancies noted in the shower wall and tiled floor surfaces.



Kitchen

1. Cook top condition

MAINT PREV MONIT DEFR DEFIC

X

X

- Gas cook top noted and operated normally when tested.
- The self igniter is not working correctly and needs to be serviced or replaced.





2. Oven & Range MAINT PREV MONIT DEFR DEFIC

Observations:
• The gas oven was tested at the time of inspection and appeared to function properly.





3. Sinks

MAINI	PREV	MONII	DEFR	DEFIC	
					Observations:
					• The sink and related components are functional





4. Counters

MAINT	PREV	MONIT	DEFR	DEFIC

Observations:

- Appeared functional at the time of inspection.
- Plastic laminate tops noted.
- The gap between the counter and the splashback requires sealing to prevent moisture intrusion into the cupboards.



5. Cabinets

MAINT	PREV	MONIT	DEFR	DEFIC
Χ		Х		

- Appeared functional and in satisfactory condition.
 Some moisture damage was noted on the shelving under the kitchen sink. No leaks were noted at the time of the inspection and the area tested dry. Some maintenance is required. Monitor for any signs of water ingress.







6. Vent Condition

IVIAIIVI	FKEV	IVIOINI	DEFK	DEFIC

Materials:

• The exhaust fan is functional.



Laundry

1. Cabinets

OI	DEFIC	DEFR	MONII	PREV	MAINI
Observations:					
 Appeared full 		l			

• Appeared functional and in satisfactory condition, at the time of inspection.





2. Wash Basin

MAINI	PREV	MONII	DEFR	DEFIC
		I		
		I		

Observations:

• The sink and related components are functional unless otherwise noted.



Electrical

1. Electrical Panel

MAINT	PREV	MONIT	DEFR	DEFIC
				1 1
				1 1

Location:

- Main Panel Location:
- Exterior of structure.
- South side of the house.

Observations:

• There are at least 2 RCD's installed which protect both the power point and light circuits. This complies with current regulatory requirements.







2. Power points

MAINT	PREV	MONIT	DEFR	DEFIC

Comments:

- All tested interior and exterior power points were functional unless otherwise noted.
- Our inspection was limited to visible and accessible outlets only. Those outlets that were concealed or inaccessible due to stored items, furniture, etc. were not tested or inspected. Only a representative sampling of outlets were tested.



3. Lights and Switches

MAINT	PREV	MONIT	DEFR	DEFIC	Comments:
					Comments:
					• All tested interior and exterior light fixtures and switches were functional
					unless noted.





Gas

1. Gas fittings

MAINT PREV MONIT DEFR DEFIC Materials:

• Gas bayonet and both low and high vents are installed. The bayonet is located in the lounge room.







Water Heater

1. Water Heater Condition

	MAINT	PREV	MONIT	DEFR	DEFIC
Γ					
ı					l
П					l

Heater Type:

- Instantaneous gas hot water heater system.
- Location:
- Exterior.

Observations:

- Please note that we only inspect & comment on the operational and safety issues of the hot water system. Issues relating to compliance to relevant codes and standards, and/or installation compliance is excluded from the scope of the inspection.
- No major system safety or function concerns noted at time of inspection.



Exterior Areas

1. Doors

MAINT	PREV	MONIT	DEFR	DEFIC
X		l x l		

- Operated exterior doors were functional at the time of the inspection unless otherwise noted.
- Car port store room door frame is corroded. Requires maintenance.





2. Eaves & Fascia

MAINT PREV MONIT DEFR DEFIC

Observations:

The eaves are in satisfactory condition.
Some weathered timber noted. Recommend review for maintenance as required.







3. Walls

MAINT PREV MONIT DEFR DEFIC

Materials:

• The brick wall covering is in a satisfactory condition.






Grounds

1. Driveway and Walkway Condition

		Materials: • Brick paved driveway noted
 		N





2. Grading and Drainage

IVIZALIATI	1 1 \ L V	IVICIALI	DELLIK	DLITO	. 🔼 L
					Observations:
					 Surface drainage

• Surface drainage conditions within 3 metres of the inspected structure appeared satisfactory given the prevailing weather conditions at the time of inspection. There was no evidence noted of water pooling at or around the building structure. These areas should be monitored during periods of heavy rainfall for a full representation of drainage conditions.



3. Fence Condition

MAINT	PREV	MONIT	DEFR	DEFIC	
					I۱
ΙXΙ		ΙXΙ			•

Materials:

- Brick.
- Super 6.
- Metal.
- Unless otherwise noted, the perimeter fence appeared functional at the time of the inspection.

 Observations:

• Front metal railing needs reattched to the brick pier on one section.








4. Balcony Structure

MAINT	PREV	MONIT	DEFR	DEFIC	_
					ľ
				l	ŀ

Observations:

• No deficiencies noted. Appears to be structurally sound.







5. Main Gas Valve Condition

MAINT	PREV	MONIT	DEFR	DEFIC	1
					Location:
					 Front of structure




Garage

1. Garage and Shed

IVIAIIVI	PREV	MONT	DEFR	DEFIC	NA - (- 2 - 1 -
					Materials:
					 The attached carport appears functional and structurally sound
		•	•	•	The rear store room appears to be structurally sound







Resicert Service Agreement

Resicert Inspection and Service Agreement - October 2021

- 1.0 Acceptance of Agreement: The Client has made a booking, accepted the quotation and the inspector arrives on site to commence the inspection, the Client is deemed to accept this agreement as to the basis of the inspection being undertaken. This agreement takes precedence over any previous oral or written representations by Resicert.
- 2.0 Payment Terms : Full payment of the inspection is required prior to the inspection report and summary being provided to the Client.
- 3.0 Purpose of Inspection: The purpose of the inspection is to provide advice to the Client in relation to the condition of the property at the time of the inspection. This report is not an all encompassing report dealing with the building from every aspect. It is a reasonable attempt to identify any obvious or significant defects apparent at the time of the inspection.
- 4.0 Scope of Inspection: Scope of inspection will depend on the inspection type which the Client has selected. Prepurchase inspections are undertaken in accordance with AS 4349.1 2007 Inspection of buildings Part 1: Pre-purchase inspections— Residential buildings unless otherwise stated below.
- 4.1 Basic and Standard Inspections: The inspection shall comprise visual appraisal and limited assessment of accessible areas of the property to identify major defects to the building structure and to form an opinion regarding the general condition of the structure of the property.

It is not required to contain any assessment or an opinion regarding the following:



-Any non-structural element, e.g., roof plumbing and roof covering, general gas, water an sanitary plumbing, electrical wiring, partition walls, cabinetry, windows, doors, trims, fencing, minor structures, non-structural damp issues, ceiling linings, floor coverings, decorative finishes such as plastering, painting, tiling, etc. -An assessment of any aspect or component of the property that cannot be seen or that requires testing and/or measurement to determine soundness. - Any area or item that was not, or could not be, observed by the inspector. -General maintenance other than that which is deemed to be directly related to the ongoing structural performance of the property. -Serviceability damp defects such as condensation, rising damp, lateral damp, falling damp should only be assessed and reported on where structural damage has occurred, is occurring, or may occur.

- 4.2 Plus Inspection: Residert shall inspect accessible parts of the building and appurtenances, together with relevant features of the property within 30m of the building and within the boundaries of the site, or as otherwise agreed in the inspection agreement. In this context, relevant features include car accommodation, detached laundry, and garden sheds, retaining walls more than 700 mm high, paths and driveways, steps, fencing, earth embankments, surface water drainage and storm water run-off.
- 4.3 Safety Barrier and Pool Condition Inspection (WA) as an add-on or stand alone: Inspection is completed in accordance with the Western Australian Private Swimming Pool Inspector Guidelines Inspecting Private Swimming Pool Spa Enclosures Second edition 24 July 2007 / Pool Safety Inspection (QLD &VIC) as a Compliance Inspection or Advisory only: inspection and report in accordance with AS1926 1&2-2007 and QDC MP3.4: Inspector has the right not to test or inspect any component if they believe that through operation or testing it may cause damage or is a potential safety issue. -Require permission, necessary access and any required components to operate or inspect items as outlined for this inspection - Unless otherwise advised we will assume that all components can be operated and will not be damaged when doing so. No liability relating to operating a component during the inspection. - Require applicable operational manual and/or instructions relating to the inspection of any component. -If we are required to start up or turn on any component, it will be necessary to have required start up information. Otherwise we reserve the right not to operate. -information contained in the WA Safety Barrier and Pool Condition Report (as an add-on or a stand alone) or a QLD &VIC Advisory Only Report is an information document only and will articulate potential issues that are likely to be flagged as deficient by council in the process of achieving required certification for the pool. It is not always possible to operate pumps. For pools and spas (excluding bath type spas located in bathrooms) to be tested must have a minimum level of water prior to commencement of inspection. Resicert accepts no liability for any subsequent drownings or accidents resulting in death or injury that may result from the advise provided in the Safety Barrier and Pool Condition Report. The Recommendations made in the report are for information only and Resicert will not seek compliance on behalf of any third party.
- 4.4 SMOKE ALARMS (QLD) it is a requirement from 31 December 2021 that all rental properties are fitted with interconnected photoelectric smoke alarms, and from 31 December 2026 that all homes are fitted with interconnected photoelectric smoke alarms. These alarms must be installed in every bedroom, in hallways and on every level.
- 5.0 Extent of Reporting: Significant items to be reported are as follows: (a) Major defects as defined in AS 4349.1. (b) A general impression regarding the extent of minor defects. (c) Any major defect that is an urgent and a serious safety hazard.

6.0 Safe and Reasonable Access: This is a visual inspection only. The extent of accessible areas shall be determined by



the inspector at the time of inspection, based on the conditions encountered at the time of inspection. The inspector shall also determine whether sufficient space is available to allow safe access. This will apply to roof spaces and underfloor access. The inspection shall include only accessible areas and areas that are within the inspector's line of sight and close enough to enable reasonable appraisal. Roof inspection by walking upon the roof will be limited to single storey dwellings which are safely accessible with the use of a 3.6 metre ladder, and only when the slope, roof condition and climate do not reduce safety.

7.0 Exclusions from Inspection: Resicert need not inspect or report on the following items:Footings below the ground or concealed damp-proof course - the structural design or adequacy of any element of construction. - Electrical installations, smoke detectors, light switches and fittings, TV, sound and communications - Concealed plumbing, gas fittings and fixtures. - Whether the building complies with the provisions of any building Act, code, regulation(s) or by-laws. - Air-conditioning, alarm and intercom systems, automatic garage door mechanisms. - Swimming pools, pool fencing and associated filtration and similar equipment. - The operation of fireplaces and solid fuel heaters, including chimneys and flues. - Soft floor coverings. - Electrical appliances including dishwashers, incinerators, ovens, ducted vacuum - Paint coatings, except external protective coatings. - Health hazards (e.g., allergies, soil toxicity, lead content, presence of asbestos). - Timber and metal framing sizes and adequacy and concealed tie-downs and bracing. - Timber pest activity. - Other mechanical or electrical equipment (such as gates, inclinators). - Soil conditions and control joints. - Sustainable development provisions. - Concealed framing-timbers or any areas concealed by wall linings/ sidings. - Lands

For Western Australian Residential Properties built pre-1970's, we recommend an electrical inspection to ensure the Roof cabling is satisfactory.

- 8.0 Liability and Limitations: The Resicert report does not constitute a guarantee in relation to the property. It is a limited opinion of condition of the inspected property at the time of inspection. Resicert's liability in relation to the inspection and report will be limited to a refund of the inspection fee. The inspection and report is undertaken for the Client named on the report. No responsibility is accepted to any third party.
- 9.0 Money Back Guarantee: If the client is not fully satisfied with the building inspection and/or building inspection report provided, Resicert will refund 100% of the building inspection fee to the client. This will require the client to complete the request for a refund application form and agree to the conditions there-in stated prior to a refund. This guarantee only applies for a period of 60 days from the date of the inspection. After this period it is at the full discretion of Resicert whether a request for a refund will be approved.
- 10.0 Follow up inspections: The initial fee does not allow for any follow up visits, if required, to the residence. A quote to undertake this activity will be provided if necessary.
- 11.0 Estimates Provided: Any estimates or budgets provided relating to work required to be undertaken is purely to provide an indication of approximate costings. The figures provided are not a quotation or estimate to carry out any works and can not be relied upon for this purpose. All estimates and budgets which are provided are done so only on this basis, and no liability, with the client or any third party, whatsoever will be accepted in relation to budgets and estimates provided, unless otherwise stated.

12.0 Probable Costings: Any probable costings outlined represent an opinion of renovation costs only which can vary



considerably depending on range of factors including but not limited to:

Type and standard of materials, fittings and fixtures chosen. -Level of of client involvement and engagement required - Construction method and process chosen -Overall timings and duration of works undertaken -Fluctuations in building materials and labour costs -Scale and extent of the renovation project -When the renovation project is undertaken - Location of the works and site conditions

The probable costings provided is based on standard rates for previous projects and is not an elemental or detailed estimate. A detailed estimate of this nature can be provided by a Quantity Surveyor or through obtaining quotations from appropriate suppliers and tradesman.

13.0 Approvals for access to property: The Client represents and assures Resicert that the Client has secured all approvals necessary for entry onto the premises to be inspected. Client further agrees to defend, indemnify and hold harmless Resicert from demands or claims alleging a trespass upon the premises to be inspected. It is the responsibility of the Client or Agent to ensure the utilities are on at the time of inspection. Resicert recommends checking for permits on all additional construction performed on the property after the original construction.

14.0 Termite/Pest Inspection Coordination: (1) Resicert Property Inspections does not carry out all of the pest Inspection services in NSW, VIC, SA or produce the written report. This is the case if the logo at the top of the report does not say Resicert. (2) Resicert simply conveys orders to independent companies for completion in these cases. (3) All pest Inspection providers have current professional indemnity insurance. The Client and the provider indemnify Resicert to and from any, omissions, errors, damage, consequences and legal action resulting from the pest inspection services and reports. (4) Resicert does not carry professional indemnity insurance which relates to pest inspection services if a third party company conducts the inspection. (5) Resicert cannot and does not accept liability in relation to the pest Inspection providers service, and / or content of written reports or warranties which may be provided in the event of delivery by a third party company. The Client's acceptance of the pest inspection coordination service that Resicert provides is done so based on your full understanding and acceptance of these conditions.

15.0 Proprietary Rights: The report, contents, comments and format of this inspection report are the proprietary rights of Resicert Property Inspections and subject to copyright law. Unlawful duplication can result in penalties.

16.0 Asbestos Disclaimer: If during the course of the inspection asbestos or materials containing asbestos happened to be noticed then this may be noted. Many building materials for many years contained or were comprised entirely of asbestos material. Approximate dates for legal disuse include: sprayed/lagging - late 1970s, cement sheeting - 1982, corrugated sheeting - 1984, other asbestos cement products - 1986, gaskets - 1997, friction pads - 2003. While your inspector may indicate that there may be some suspected asbestos material at the property, any property constructed prior to 2004 may have elements of asbestos in the materials, lagging, insulation, cement sheeting, piping, floor coverings, floor underlay, expansion joints, caulking, sink pads, toilet systems, pipe insulation, gaskets, gasket insulation and more materials and locations around the home. The only conclusive way to determine if asbestos is present in the home or as a part of the materials in the home is to take a sample and have it professionally tested. This sampling falls outside of the scope of this inspection. Sheeting and asbestos materials should fully sealed. If it is damaged, it should be dealt with immediately. If asbestos is noted as present within the property you should then seek advice from a qualified asbestos removal expert for further details and information on this material. Drilling, cutting or removing products



containing asbestos is a high risk to peoples health and the Client should seek advice from a qualified asbestos removal expert.

17.0 Not a "Certificate of Building Compliance" report (For reports within ACT): The report may contain copies of any approved plans, building approvals, building permit and Certificates of Occupancy and act as a compliance report for the purposes of "Building and Compliance". However, any comments made by the person who prepared the report as to whether or not, in the opinion of the inspector, the structures on the land substantially comply with the approved plans (if any) are made on the basis of a review of the plans and the visually accessible parts of the property at the time of the inspection.

18.0 Ownership rights :Resicert retains ownership and all rights to the inspection report. Resicert has the rights to all data collected during the inspection and compiled in the report. Resicert has the right to on-sell the inspection report to 3rd parties subject to removal of any specific Client details. All rights reserved.

19.0 In the event that a defect is identified that has not been documented in this report, Resicert must be notified before any remedial work is undertaken. No Liability shall be accepted where remedial action is taken prior to Resicert being advised of the defect and given the opportunity to re-inspect the property and identify the defect.

[10-17]



Glossary

Term	Definition
Valley	The internal angle formed by the junction of two sloping sides of a roof.
Valley Flashing	Sheet metal or other material used to line a valley in a roof to direct rainwater down into the gutter system.

